

# ISO 14952-3:2003-11 (E)

## Space systems - Surface cleanliness of fluid systems - Part 3: Analytical procedures for the determination of non-volatile residues and particulate contamination

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>4</b>	<b>Acceptance inspection .....</b>	<b>2</b>
4.1	General .....	2
4.2	Visual inspection .....	2
4.3	Acidity and alkalinity test .....	2
4.4	Acceptance inspection of items cleaned in a controlled environment .....	2
4.5	Acceptance inspection of items cleaned in the field .....	6
4.6	Acceptance inspection of packaging materials .....	7
4.7	Acceptance inspection of items by functional test .....	9
<b>5</b>	<b>Sampling and analytical practices .....</b>	<b>9</b>
5.1	Cleanliness level test methods .....	9
5.2	Microscopic particle population .....	12
5.3	Gravimetric NVR analysis method .....	12
5.4	Aqueous ultrasonic sampling and total carbon (TC) NVR analysis .....	13
<b>Annex A (informative) Sensitivity factor calculation .....</b>		<b>15</b>