

ISO 5398-3:2007-08 (E)

Leather — Chemical determination of chromic oxide content —
Part 3: Quantification by atomic absorption spectrometry

Contents		Page
Foreword.....		iv
Introduction		v
1 Scope		1
2 Normative references		1
3 Terms and definitions		1
4 Principle.....		1
5 Sampling and sample preparation		2
6 Reagents.....		2
6.1 Wet oxidation method		2
6.2 Atomic absorption spectrometry		2
7 Apparatus		2
8 Methods		3
8.1 Preparation of analytical solution.....		3
8.2 Measurement of the aqueous solution.....		3
9 Calculation and expression of results.....		4
10 Test report		5
Annex A (informative) Determination of water and other volatile matter		6