

ISO 5398-4:2007-08 (E)

Leather — Chemical determination of chromic oxide content —
Part 4: Quantification by inductively coupled plasma – optical emission spectrometer (ICP-OES)

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	2
5	Sampling and sample preparation	2
6	Reagents	2
6.1	Wet oxidation method	2
6.2	ICP-OES	2
7	Apparatus	2
8	Methods	3
8.1	Preparation of analytical solution	3
8.2	Measurement of the aqueous solution	3
9	Calculation and expression of results	4
10	Test report	5
Annex A (informative) Determination of water and other volatile matter		6