

# DIN 50969-1:2009-06 (E)

## Prevention of hydrogen-induced brittle fracture of high-strength steel building elements - Part 1: Advice on the prevention

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
Introduction .....		4
1	<b>Scope .....</b>	<b>5</b>
2	<b>General .....</b>	<b>5</b>
3	<b>Measures to be taken at the design and manufacturing stages .....</b>	<b>5</b>
3.1	<b>Design measures .....</b>	<b>5</b>
3.2	<b>Material-related measures .....</b>	<b>5</b>
3.3	<b>Manufacture-related measures .....</b>	<b>6</b>
3.4	<b>Minimizing residual tensile stresses .....</b>	<b>6</b>
4	<b>Coating process .....</b>	<b>6</b>
4.1	<b>General .....</b>	<b>6</b>
4.2	<b>Pretreatment for activation of the surface for subsequent coatings .....</b>	<b>7</b>
4.3	<b>Coating .....</b>	<b>7</b>
4.4	<b>Heat treatment after coating .....</b>	<b>7</b>
Bibliography .....		8