

# DIN 52108:2010-05 (E)

## Testing of inorganic non-metallic materials - Wear test using the grinding wheel according to Böhme - Grinding wheel method

---

<b>Contents</b>		<b>Page</b>
	<b>Foreword</b> .....	<b>3</b>
<b>1</b>	<b>Scope</b> .....	<b>4</b>
<b>2</b>	<b>Normative references</b> .....	<b>4</b>
<b>3</b>	<b>Terms and definitions</b> .....	<b>4</b>
<b>4</b>	<b>Principle</b> .....	<b>4</b>
<b>5</b>	<b>Apparatus</b> .....	<b>4</b>
<b>6</b>	<b>Specimens</b> .....	<b>7</b>
<b>7</b>	<b>Procedure</b> .....	<b>7</b>
<b>8</b>	<b>Evaluation</b> .....	<b>9</b>
<b>9</b>	<b>Test report</b> .....	<b>10</b>