

ISO 9717:2010-12 (E)

Metallic and other inorganic coatings - Phosphate conversion coating of metals

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	2
4	Information to be supplied by the purchaser to the processor	3
4.1	Essential information	3
4.2	Additional information	3
5	Designation	3
5.1	General	3
5.2	Designation specifications	4
5.3	Designation of heat treatment requirements	4
5.4	Classification of phosphate conversion coating	5
6	Requirements	6
6.1	Surface preparation	6
6.2	Phosphate conversion coating	6
6.3	Processing after phosphating	6
6.4	Thickness of coating	7
6.5	Stress-relief heat treatment before cleaning and phosphating	8
6.6	Hydrogen-embrittlement-relief heat treatment after phosphating	8
6.7	Treatments for supplementary coatings	8
6.8	Adhesion of phosphate conversion coatings	9
6.9	Quality-evaluation test of phosphate conversion coatings	9
7	Sampling	9
Annex A (informative)	Methods of application, characteristics and significance of phosphate conversion coatings	10
Annex B (informative)	Determination of rinse-water contamination	13
Annex C (informative)	Identification of phosphate conversion coating	15
Annex D (normative)	Salt droplet test	17
Annex E (normative)	Determination of resistance of phosphate conversion coating to neutral salt spray (fog) test	20
Annex F (normative)	Treatments for supplementary coating	22
Bibliography		23