

DIN EN 16016-4:2012-01 (E)

Non destructive testing - Radiation methods - Computed tomography - Part 4: Qualification

Contents		Page
Foreword		3
Introduction		4
1	Scope	5
2	Normative references	5
3	Terms and definitions	5
4	Qualification of the inspection	5
4.1	General	5
4.2	Qualification of defect testing	5
4.2.1	General	5
4.2.2	Quality feature	5
4.2.3	Feature detectability/test system/system parameterisation	6
4.2.4	Verification of suitability	7
4.2.5	Consistency check	7
4.2.6	Documentation	7
4.3	Qualification of dimensional testing	8
4.3.1	General	8
4.3.2	Test and measurement task	8
4.3.3	Dimensional testing/test system/system parameterisation	8
4.3.4	Degree of accuracy	9
4.3.5	Consistency check	9
4.3.6	Documentation	9
5	Qualification of the CT system	9
5.1	General	9
5.2	Integral overall system test	10
5.3	Checking the system components	10
5.3.1	General	10
5.3.2	Manipulation system	10
5.3.3	Image scale	10
5.3.4	Beam axis perpendicularity	10
5.3.5	Tube focal spot	10
5.3.6	Tube stability	10
5.3.7	Detector	11
5.3.8	Reconstruction	11
5.3.9	Visualisation	11
5.4	Documentation	11
6	Example of CT system resolution evaluation methods	11
6.1	Pre-amble	11
6.2	Acquisition parameters	12
6.3	Recommendations for creating reference objects	12
6.4	Density resolution measurement method	12
6.4.1	General	12
6.4.2	High energy reference object	13
6.4.3	Low energy reference object	13
6.4.4	Experimental measurements	13