

ISO 1352:2011-04 (E)

Metallic materials - Torque-controlled fatigue testing

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Symbols and abbreviated terms	3
5	Principle of test	3
6	Test plan	4
7	Shape and size of specimen	4
7.1	Form	4
7.2	Dimensions	5
8	Preparation of specimens	6
8.1	General	6
8.2	Machining procedure	6
8.3	Sampling and marking	6
8.4	Surface conditions of specimen	7
8.5	Dimensional checks	7
8.6	Storage and handling	7
9	Apparatus	7
9.1	Testing machine	7
9.2	Instrumentation for test monitoring	9
10	Test procedure	9
10.1	Mounting of specimen	9
10.2	Speed of testing	9
10.3	Application of torque	9
10.4	Calculation of nominal torsional stress	10
10.5	Recording of temperature and humidity	10
10.6	Failure and termination criteria	10
11	Test report	10
Annex A (informative) Presentation of results		14
Annex B (informative) Verification of alignment of torsional fatigue testing machines		18
Annex C (informative) Measuring uniformity of torsional strain (stress) state		20
Bibliography		23