

DIN EN ISO 10863:2011-12 (E)

Non-destructive testing of welds - Ultrasonic testing - Use of time-of-flight diffraction technique (TOFD) (ISO 10863:2011)

Contents		Page
Foreword		3
1	Scope	4
2	Normative references	4
3	Terms and definitions	5
4	General remarks on the capabilities of the technique	5
5	Testing levels	6
6	Information required prior to testing	6
6.1	Items to be defined by specification	6
6.2	Specific information required by the operator before testing	7
6.3	Written test instruction or procedure	7
7	Requirements for personnel and equipment	7
7.1	Personnel qualifications	7
7.2	Equipment	8
8	Preparation for testing	8
8.1	Volume to be inspected	8
8.2	Setup of probes	9
8.3	Scan increment setting	9
8.4	Geometry considerations	9
8.5	Preparation of scanning surfaces	9
8.6	Temperature	10
8.7	Couplant	10
8.8	Provision of datum points	10
9	Testing of base material	10
10	Range and sensitivity settings	11
10.1	Settings	11
10.2	Checking of the settings	11
10.3	Reference blocks	12
11	Weld testing	13
12	Interpretation and analysis of TOFD images	13
12.1	General	13
12.2	Assessing the quality of the TOFD image	13
12.3	Identification of relevant TOFD indications	14
12.4	Classification of relevant TOFD indications	14
12.5	Determination of location and size	15
12.6	Evaluation against acceptance criteria	16
13	Test report	16
Annex A (informative)	Reference blocks	18

Annex B (informative) Examples of TOFD scans	23
Bibliography	33