

# ISO 20903:2011-11 (E)

## Surface chemical analysis - Auger electron spectroscopy and X-ray photoelectron spectroscopy - Methods used to determine peak intensities and information required when reporting results

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Symbols and abbreviated terms .....	1
5	Methods for peak intensity determination -- Direct spectrum .....	1
5.1	General .....	1
5.2	Selection and subtraction of an inelastic background .....	3
5.3	Measurement of peak intensity .....	3
5.4	Measurement of a peak intensity with computer software .....	4
5.5	Measurement of peak intensities for a spectrum with overlapping peaks .....	5
5.6	Uncertainty in measurement of peak area .....	5
6	Methods for peak intensity determination -- Augerelectron differential spectrum .....	6
6.1	General .....	6
6.2	Measurement of Augerelectron differential intensity .....	6
6.3	Uncertainties in measurement of Augerelectron differential intensity .....	7
7	Reporting of methods used to measure peak intensities .....	8
7.1	General requirements .....	8
7.2	Methods used to determine peak intensities in direct spectra .....	8
7.3	Methods used to obtain and determine peak intensities in Augerelectron differential spectra .....	9
Annex A (informative)	Instrumental effects on measured intensities .....	10
Annex B (informative)	Useful integration limits for determination of peak intensities in XPS spectra .....	11
Bibliography .....		13