

ISO 13588:2012-10 (E)

Non-destructive testing of welds - Ultrasonic testing - Use of automated phased array technology

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	2
4	Testing levels	2
5	Information required prior to testing	4
5.1	Item to be defined prior to procedure development	4
5.2	Specific information required by the operator before testing	4
5.3	Written test procedure	4
6	Requirements for personnel and equipment	5
6.1	Personnel qualifications	5
6.2	Equipment	5
7	Preparation for testing	5
7.1	Volume to be inspected	5
7.2	Verification of test set-up	6
7.3	Scan increment setting	6
7.4	Geometry considerations	6
7.5	Preparation of scanning surfaces	6
7.6	Temperature	6
7.7	Couplant	6
8	Testing of base material	7
9	Range and sensitivity settings	7
9.1	Settings	7
9.2	Checking of the settings	8
9.3	Reference blocks	8
10	Equipment checks	9
11	Procedure qualification	9
12	Weld testing	9
13	Data storage	10
14	Interpretation and analysis of phased array data	10
14.1	General	10
14.2	Assessing the quality of the phased array data	10
14.3	Identification of relevant indications	10
14.4	Classification of relevant indications	10
14.5	Determination of location and length of an indication	11
14.6	Indication assessment	11
14.7	Evaluation against acceptance criteria	11

15	Test report	11
	Annex A (informative) Typical reference blocks and reference reflectors	13
	Bibliography	17