

DIN 25457-4:2013-04 (Englisch)

Activity measurement methods in the clearance of radioactive substances and components of nuclear facilities - Part 4: Contaminated and activated metal scrap

Contents		Page
Foreword		3
1	Scope	4
2	Normative references	4
3	Terms and definitions	4
4	Clearance strategy and preliminary examination	5
4.1	Specification of clearance strategy	5
4.2	Principles of preliminary examination	6
4.3	Spatial distribution of activity	8
4.4	Radionuclide mixture	8
4.5	Key nuclides and scaling factors and use of summation rule	8
4.6	Nuclide vector	9
4.7	Effects of decontamination	10
5	Method of decision measurement	10
5.1	General	10
5.2	Measurement of surface activity	12
5.3	Collimated in-situ gamma spectrometry	13
5.3.1	General	13
5.3.2	Field of application	13
5.3.3	Requirements for the measurement set-up for measurements on packages	15
5.3.4	Calibration	15
5.3.5	Performance of measurements	16
5.4	Activity measurement after smelting	17
5.4.1	General	17
5.4.2	Determination of activity	17
5.5	Measurement of total gamma activity	17
6	Documentation	18
6.1	General	18
6.2	Preliminary examination	19
6.3	Decision measurement	20
Annex A (normative)	Averaging quantities for decision procedures	22
A.1	General	22
A.2	Averaging mass in decision procedures	22
A.3	Averaging area in decision procedures	22
Annex B (informative)	Examples of nuclide vectors	24
Annex C (informative)	Examples for the calculation of scaling factors when results are available for a set of samples	26
Annex D (informative)	Partitioning factors of significant radionuclides when smelting metals with respect to product metal (smelt), slag and dust	30
Annex E (informative)	Examples for the calculation of minimum thickness to convert area-related activity to mass-related activity	31
Bibliography		32