

ISO 9513:2012-12 (E)

Metallic materials - Calibration of extensometer systems used in uniaxial testing

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Terms and definitions	1
3	Symbols and designations	1
4	Principle	2
5	Calibration equipment	2
5.1	Calibration apparatus	2
5.2	Calibration traceability	2
6	Pre-calibration inspection	2
6.1	Objective	2
6.2	Records of the inspection	3
6.3	Identification of extensometer system elements	3
7	Measurement of extensometer gauge length	3
7.1	Fixed gauge length extensometry	3
7.2	Variable gauge length extensometry	3
7.3	Non-contacting extensometry	4
7.4	Extensometer gauge lengths established using setting gauges	4
8	Calibration process	4
8.1	Environmental considerations	4
8.2	Position of the extensometer	4
8.3	Calibration increments	4
8.4	Calibration process	6
8.5	Determination of the characteristics of the extensometer system	6
9	Classification of the extensometer system	7
9.1	Input data	7
9.2	Analysis of the data	7
9.3	Classification criteria	7
9.4	Assessment of the results	7
10	Uncertainty determination	8
10.1	Uncertainty of the calibration	8
10.2	Uncertainty budget determination	8
11	Extensometer system calibration intervals	8
12	Calibration certificate	8
12.1	Mandatory information	8
12.2	Data presentation	9
Annex A (informative)	Uncertainty of measurement	10

Annex B (informative) Calibration of the calibration apparatus	15
Annex C (informative) Example of a report of the calibration of calibration apparatus	17
Annex D (informative) Examples of extensometer system configurations	20
Annex E (informative) Laser extensometry	29
Annex F (informative) Video extensometry	37
Annex G (informative) Full field strain measurement video extensometry	41
Annex H (informative) Calibration of a cross-head measurement system	43
Bibliography	44