

ISO 17636-1:2013-01 (E)

Non-destructive testing of welds - Radiographic testing - Part 1: X- and gamma-ray techniques with film

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	2
4	Symbols and abbreviated terms	3
5	Classification of radiographic techniques	3
6	General preparations and requirements	4
6.1	Protection against ionizing radiation	4
6.2	Surface preparation and stage of manufacture	4
6.3	Location of the weld in the radiograph	4
6.4	Identification of radiographs	4
6.5	Marking	4
6.6	Overlap of films	4
6.7	Types and positions of image quality indicators	4
6.8	Evaluation of image quality	5
6.9	Minimum image quality values	5
6.10	Personnel qualification	6
7	Recommended techniques for making radiographs	6
7.1	Test arrangements	6
7.2	Choice of tube voltage and radiation source	12
7.3	Film systems and metal screens	13
7.4	Alignment of beam	15
7.5	Reduction of scattered radiation	15
7.6	Source-to-object distance	15
7.7	Maximum area for a single exposure	18
7.8	Density of radiograph	18
7.9	Processing	18
7.10	Film viewing conditions	19
8	Test report	19
Annex A (normative)	Recommended number of exposures which give an acceptable examination of a circumferential butt weld	21
Annex B (normative)	Minimum image quality values	26
Bibliography		30