

DIN 25457-1:2014-12 (E)

Activity measurement methods for the clearance of radioactive substances and nuclear facility components - Part 1: Fundamentals

Contents	Page
Foreword	5
1 Scope	6
2 Normative references	6
3 Terms, definitions and symbols	7
3.1 Terms and definitions.....	7
3.2 Symbols	9
4 Measurement methods.....	13
4.1 Basic model and characteristic variables of the activity measurement methods with consideration of type A and type B measuring uncertainties.....	13
4.1.1 General information.....	13
4.1.2 Description of the model in general form	14
4.1.3 Special model approach for activity measurement method.....	15
4.1.4 Procedure for conservative and realistic approaches	17
4.2 Direct surface-total-activity measurement.....	18
4.2.1 General	18
4.2.2 Relevant type B measurement uncertainties.....	19
4.2.3 Requirements for the measurement devices	20
4.2.4 Requirements for the calibration sources	20
4.2.5 State of the surface of the measured material	21
4.2.6 Dependency of the count rate of the detector on the geometric conditions	21
4.2.7 Determination of an alarm value	21
4.2.8 Measurement procedure	23
4.2.9 Quality assurance.....	25
4.3 Indirect surface total-activity measurement	26
4.3.1 General	26
4.3.2 Relevant type B measurement uncertainties.....	26
4.3.3 Requirements for the measurement setup.....	27
4.3.4 Requirements for the calibration source	27
4.3.5 Calibration.....	27
4.3.6 Background effect determination.....	27
4.3.7 Performing the measurement.....	27
4.3.8 Quality assurance.....	28
4.4 Spectrometric measurement methods.....	29
4.4.1 Gamma spectrometry on material samples.....	29
4.4.2 In-situ gamma spectrometry	36
4.4.3 Alpha spectrometry on material samples	42
4.4.4 Determination of the activity of alpha-emitting radionuclides using gamma spectrometry on material samples.....	47
4.5 Total gamma activity measurement	47
4.5.1 General	47
4.5.2 Relevant measurement uncertainties	48
4.5.3 Requirements for measurement equipment.....	48
4.5.4 Property of the measured material.....	48
4.5.5 Requirements for the calibration	48
4.5.6 Performing the measurement.....	49
4.5.7 Detection limit, decision threshold and confidence interval.....	49
4.5.8 Quality assurance.....	50

Annex A (normative) Determination of the surface response	52
Annex B (informative) Energies and range of alpha particles	57
Annex C (informative) Determination of the activity of alpha-emitting radionuclides using gamma spectrometry on material specimens.....	59
C.1 General.....	59
C.2 Thorium decay series and Th-230	59
C.3 Uranium.....	59
C.4 Plutonium	60
Annex D (informative) Explanations for the calculation of the decision thresholds and detection limits for the pulse counting with time preselection.....	64
Annex E (informative) Explanations for the calculation of the detection limit and decision threshold for stationary pulse rate measurements	69
Annex F (informative) Explanations for the calculation of the detection limit and decision threshold for dynamic pulse rate measurement.....	79
Annex G (informative) Explanations for the calculation of the decision thresholds and detection limits for the pulse counting with time preselection at small pulse numbers, e.g. alpha surface activity measurement.....	82
Annex H (informative) Calculation of the detection limit and decision threshold, the upper limit of the confidence interval and the expected value for measurements using contamination monitors with consideration of type B measurement uncertainties.....	84
H.1 Basic measurement model	84
H.2 Measurement task and measurement parameters	85
H.3 Calculation of the characteristic variables.....	86
H.4 Interpretation of the results in respect of the decision measurement for the clearance.....	87
H.5 Integration of uncertainties in respect of the clearance level of the area-specific total activity	88
Annex I (informative) Calculation of the detection limit and decision threshold for measurements with wipe test measurement setups (indirect total surface activity measurement)	89
Annex J (informative) Calculation of the detection limit and decision threshold, the upper limit of the confidence interval and the expected value for gamma spectrometry and in-situ gamma spectrometry	92
J.1 Preliminary remarks.....	92
J.2 Measurement of site grounds according to DIN 25457-7: Determination of the area- specific activity as well as the nuclide-specific dose rate of Cs-137.....	92
J.2.1 General.....	92
J.2.2 Calibration factor and its standard uncertainty.....	93
J.2.3 Calculation of the nuclide-specific ambient dose equivalent rate.....	93
J.2.4 Example for the calculation of the characteristic limits as well as the best estimator and its standard uncertainty (non-collimated measurement, area-specific activity and nuclide-specific dose rate)	94
J.2.5 Summary	96
J.3 Determination of the mass-specific activity if a disturbance is present due to an interfering line as well as a line in the background effect spectrum.....	96
J.4 Determination of the Co-60 activity from very small net peak areas.....	98
Annex K (informative) Calculation of the detection limit and the decision threshold, the upper limit of the confidence interval and the expected value for total gamma activity measurements.....	104
K.1 Preliminary remarks.....	104
K.2 Essential input variables for the conservative calibration	105
K.3 Realistic calculation of decision threshold and detection limit	108
K.3.1 General	108
K.3.2 Determination of the realistic calibration factor w.....	108
K.3.3 Consideration of the reduction of the background effect due to measured material.....	108
K.3.4 Consideration of the non-counting statistical variance of the background effect	108
K.4 Best estimated values, upper limit of the confidence interval	111
K.5 Summary	114
Bibliography	116