

# DIN 50100:2016-12 (E)

## Load controlled fatigue testing - Execution and evaluation of cyclic tests at constant load amplitudes on metallic specimens and components

---

<b>Contents</b>		<b>Page</b>
Foreword .....		4
Introduction .....		5
1	Scope .....	6
2	Normative references .....	6
3	Symbols and abbreviations .....	6
4	S-N curve (Wöhler curve) .....	12
5	Load types .....	17
6	Shape of the specimens and specimen manufacturing .....	19
7	Test setup .....	21
8	Test procedure .....	22
8.1	General .....	22
8.2	High cycle fatigue .....	22
8.2.1	General .....	22
8.2.2	Pearl string method .....	26
8.2.3	Load level method .....	33
8.3	Long life fatigue strength .....	41
8.3.1	General .....	41
8.3.2	Staircase method .....	44
9	Test evaluation .....	50
9.1	General .....	50
9.2	High cycle fatigue .....	51
9.2.1	General .....	51
9.2.2	Pearl string method .....	51
9.2.3	Load level method .....	54
9.3	Evaluating long life fatigue strength .....	56
9.3.1	General .....	56
9.3.2	Staircase method .....	56
9.4	Number of cycles at knee point and course of the S-N curve in the long life fatigue regime .....	58
9.5	S-N curve for failure probabilities other than 50 % .....	59
10	Documentation .....	60
10.1	General .....	60
10.2	Material .....	61
10.3	Specimen (material sample or component) .....	61
10.4	Test setup .....	62
10.5	Test procedure .....	62
10.6	Test evaluation .....	62
10.7	S-N curve (Wöhler curve) .....	63
Annex A (normative)	Pearl string method: Determination of the required random sample size .....	64

A.1	Pearl string method: Number of specimens required for estimation of the mean number of cycles .....	64
A.2	Pearl string method: Number of specimens required for estimation of the slope kGG of the S-N curve .....	70
Annex B (normative) Load level method: Determination of the required random sample size .....		76
B.1	Load level method: Required number of specimens from the entire test series for estimation of the mean number of cycles .....	76
B.2	Load level method: Number of specimens from the entire test series required for estimation of the slope of the S-N curve in the high cycle fatigue regime .....	82
Annex C (informative) Typical standard deviations in the high cycle fatigue regime .....		88
Annex D (informative) Examples of test protocols .....		89
D.1	Record sheet for a high cycle fatigue test series .....	90
D.2	Record sheet for a long life fatigue strength test series .....	91
Annex E (normative) Examples of test evaluations .....		92
E.1	Example: Evaluation of the S-N curve in the high cycle fatigue regime obtained using the pearl string method .....	92
E.1.1	Test results .....	92
E.1.2	Position and slope of the S-N curve in the high cycle fatigue regime .....	93
E.1.3	S-N curve in the high cycle fatigue regime for a failure probability of 50 % .....	94
E.1.4	Standard deviation of the test results .....	94
E.1.5	S-N curve in the high cycle fatigue regime for a failure probability of 10 % .....	96
E.1.6	S-N curve in the high cycle fatigue regime for a failure probability of 90 % .....	96
E.1.7	Graphical representation of the S-N curve in the high cycle fatigue regime .....	97
E.2	Example: Evaluation of the S-N curve in the high cycle fatigue regime obtained using the load level method .....	97
E.2.1	Test results .....	97
E.2.2	Mean and standard deviation for load level 1 .....	98
E.2.3	Mean and standard deviation for load level 2 .....	99
E.2.4	S-N curve in the high cycle fatigue regime for a failure probability of 50 % .....	100
E.2.5	S-N curve for a failure probability of 10 % .....	100
E.2.6	S-N curve in the high cycle fatigue regime for a failure probability of 90 % .....	101
E.2.7	Graphical representation the S-N curve in the high cycle fatigue regime .....	101
E.3	Example: Evaluation of the long life fatigue strength obtained using the staircase method .....	102
E.4	Example: Determination of the number of cycles at knee point and of the course of the S-N curves up to the ultimate number of cycles .....	104
E.4.1	Pearl string method .....	104
E.4.2	Load level method .....	105
E.5	Example: Graphical representation of the S-N curve .....	107
E.5.1	Pearl string method .....	107
E.5.2	Load level method .....	109
Bibliography .....		112