

# DIN EN ISO 22825:2018-02 (E)

## Non-destructive testing of welds - Ultrasonic testing - Testing of welds in austenitic steels and nickel-based alloys (ISO 22825:2017)

---

<b>Contents</b>	<b>Page</b>
<b>European foreword</b> .....	<b>3</b>
<b>Foreword</b> .....	<b>4</b>
<b>Introduction</b> .....	<b>5</b>
<b>1 Scope</b> .....	<b>6</b>
<b>2 Normative references</b> .....	<b>6</b>
<b>3 Terms and definitions</b> .....	<b>6</b>
<b>4 Information required prior to testing</b> .....	<b>7</b>
4.1 Items to be defined by specification .....	7
4.2 Specific information required by the operator prior to testing .....	7
<b>5 Personnel</b> .....	<b>8</b>
<b>6 Test equipment</b> .....	<b>8</b>
6.1 Conventional equipment .....	8
6.2 Phased array equipment .....	8
<b>7 Range setting for compression waves</b> .....	<b>8</b>
<b>8 Sensitivity setting</b> .....	<b>9</b>
8.1 General .....	9
8.2 Use of side-drilled holes .....	10
8.3 Use of other reference reflectors .....	10
<b>9 Test procedure and ultrasonic techniques</b> .....	<b>10</b>
9.1 Development of the test procedure .....	10
9.2 Content of the test procedure .....	10
9.3 Selection of ultrasonic technique(s) .....	12
9.4 Optimization of test technique and draft of test procedure .....	13
9.5 Practical implications of the use of refracted compression waves .....	13
<b>10 Classification and sizing of indications</b> .....	<b>14</b>
<b>11 Testing of welds</b> .....	<b>14</b>
11.1 General .....	14
11.2 Surface condition and couplant fluid .....	14
11.3 Parent metal testing .....	14
11.4 Scanning .....	14
11.5 Evaluation of indications .....	15
<b>12 Test report</b> .....	<b>15</b>
12.1 General data .....	15
12.2 Information related to the test equipment .....	15
12.3 Information related to the testing technique .....	16
12.4 Results of testing .....	16
<b>Annex A (informative) Compression wave angle-beam techniques</b> .....	<b>17</b>
<b>Annex B (informative) Stainless steel calibration blocks for range setting</b> .....	<b>23</b>
<b>Annex C (informative) Reference blocks for sensitivity setting</b> .....	<b>25</b>
<b>Bibliography</b> .....	<b>28</b>