

ISO 1099:2017-06 (E)

Metallic materials - Fatigue testing - Axial force-controlled method

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Test plan	3
4.1	General outline	3
4.2	Presentation of fatigue results	4
4.2.1	General	4
4.2.2	Wöhler or S-N curve	4
4.2.3	Mean stress diagrams	4
5	Shape and size of specimen	4
5.1	Form of specimens	4
5.2	Specimen temperature measurement	5
6	Geometry	5
6.1	Bars and flat sheets >5 mm thick	5
6.2	Flat sheets	6
6.2.1	General	6
6.2.2	Thicknesses between 5 mm and 2,5 mm	6
6.2.3	Thicknesses <2,5 mm	6
6.3	Preparation of specimens	6
6.3.1	Machining procedure	7
6.3.2	Sampling and marking	7
6.3.3	Surface condition of the specimen	7
6.3.4	Dimensional checks	8
6.3.5	Storage and handling	8
7	Apparatus	8
7.1	Test machine	8
7.2	Alignment check	9
7.3	Force transducer	9
7.4	Gripping of specimen	9
8	Instrumentation for test monitoring	10
8.1	Recording systems	10
8.2	Cycle counter	10
9	Checking and verification	10
10	Mounting of specimen	10
11	Rate of testing	10
12	Application of force	11

13	Recording of temperature and humidity	11
14	Criterion of failure and test termination	11
14.1	Criterion of failure	11
14.2	Test termination	11
15	Test report	11
	Bibliography	23