

DIN 53015:2019-06 (E)

Viscometry - Measurement of viscosity using the Hoespler Falling-Ball Viscometer

Contents		Page
Foreword		4
1	Scope	5
2	Normative references	5
3	Terms and definitions	5
4	Symbols and units	5
5	Measuring range	8
6	Principle	9
7	Theory behind method	9
8	Apparatus	9
8.1	Hoespler falling-ball viscometer	9
8.2	Thermometer	11
8.3	Timer	11
8.4	Thermostat	11
8.5	Density measurement equipment	11
9	Sampling	11
10	Procedure	12
10.1	Sample preparation	12
10.2	Ball selection	12
10.3	Measuring the fall time	13
10.3.1	Preparation for measurement	13
10.3.2	Determining the fall time	13
10.3.3	Measuring the density of liquid	13
10.4	Evaluation	14
10.5	Test report	14
11	Viscometer calibration	15
11.1	Principle	15
11.2	Standards and apparatus	15
11.3	Calibration conditions	16
11.4	Number of measurements	16
11.5	Check for cleanliness and finish	16
11.6	Determining the ball density	17
11.6.1	Ball mass	17
11.6.2	Ball diameter	17
11.6.3	Ball density	17
11.7	Determining the calibration constants	17
11.8	Calibration result	18
12	Measurement uncertainty	18
12.1	General	18
12.2	Measurement uncertainty when measuring viscosity	18
12.3	Measurement uncertainty of the calibration	20

12.3.1	Measurement uncertainty of the calibration constants	20
12.3.2	Measurement uncertainty of the ball density	21
Annex A (informative) Determining measurement uncertainty		22
Bibliography		24
Figures	Figure 1 -- Höppler falling-ball viscometer (example of a design)	10
Tables	Table 1 -- Symbols and units	6
Table 2	-- Balls for use in falling-ball viscometer having a measurement tube with an inside diameter of 15,94 mm	8
Table 3	-- Minimum fall times	12
Table 4	-- Relative uncertainty of measurement (for coverage factor =) of dynamic viscosity assuming compliance with requirements in Clauses 8 to 10 and for = , as well as fall times t_1 as in Table 3	14
Table 5	-- Standard samples for viscometer calibration	15
Table 6	-- Relative variances for calibration at 20 °C and relative uncertainty of measurement (coverage factor =) for the calibration constant (applies for -° °) for calibration as specified in this document	21
Table A.1	-- Multiplication factor F1 as a function of the number of single measurements	23
Table A.2	-- Multiplication factor F2 as a function of the number of single measurements	23