

# ISO 10111:2019 (E)

## Metallic and other inorganic coatings — Measurement of mass per unit area — Review of gravimetric and chemical analysis methods

---

### Contents

	Foreword
1	Scope
2	Normative references
3	Terms and definitions
4	Principle
5	Special equipment
6	Preparation of test specimen
6.1	Size
6.2	Shape
6.3	Edge condition
6.4	Heat treatment
7	Measurement of coated area
7.1	Measurement method
7.2	Surface measuring equipment
7.2.1	Geometrical (projected) surface area
7.2.2	Surface area increase due to roughness (optional)
7.3	Number of measurements
8	Determination of mass of coating by chemical analysis
8.1	General
8.2	Restrictions
9	Gravimetric determination of mass of coating
9.1	Specimen size
9.2	Limitations
9.3	Restrictions
9.4	Gravimetric analysis equipment
9.5	Procedure
9.5.1	General
9.5.2	Difference method with dissolution of the coating
9.5.3	Direct weighing method with dissolution of the substrate
9.5.4	Difference method without dissolution
10	Calculations
10.1	Surface density
10.2	Thickness
Annex A	(informative) Reagents for selective dissolution of metal layers