

# DIN ISO 15472:2020-05 (E)

## Surface chemical analysis - X-ray photoelectron spectrometers - Calibration of energy scales (ISO 15472:2010); Text in English

---

<b>Contents</b>	<b>Page</b>
<b>Foreword</b> .....	<b>iv</b>
<b>Introduction</b> .....	<b>v</b>
<b>1 Scope</b> .....	<b>1</b>
<b>2 Normative references</b> .....	<b>1</b>
<b>3 Symbols and abbreviated terms</b> .....	<b>1</b>
<b>4 Outline of method</b> .....	<b>2</b>
<b>5 Procedure for calibrating the energy scale</b> .....	<b>5</b>
5.1 Obtaining the reference samples.....	5
5.2 Mounting the samples.....	6
5.3 Cleaning the samples.....	6
5.4 Choosing the spectrometer settings for which energy calibration is required .....	6
5.5 Operating the instrument.....	6
5.6 Options for initial or subsequent calibration measurements .....	7
5.7 Measurements for the peak binding-energy repeatability standard deviation and the scale linearity .....	7
5.8 Calculating the peak binding-energy repeatability standard deviation .....	8
5.9 Checking the binding-energy scale linearity .....	11
5.10 Procedure for the regular determination of the calibration error.....	12
5.11 Procedures for correction of the instrument binding-energy scale .....	13
5.12 Next calibration.....	15
5.13 Establishing the calibration interval.....	15
<b>Annex A (normative) Least-squares determination of the peak binding energy by a simple computational method</b> .....	<b>16</b>
<b>Annex B (informative) Derivation of uncertainties</b> .....	<b>19</b>
<b>Annex C (informative) Citation of the uncertainties of measured binding energies</b> .....	<b>21</b>
<b>Annex D (informative) Measurements of modified Auger parameters measured using XPS instruments equipped with a monochromated Al X-ray source</b> .....	<b>23</b>
<b>Bibliography</b> .....	<b>26</b>