

DIN ISO 15472:2020-05 (E)

Surface chemical analysis - X-ray photoelectron spectrometers - Calibration of energy scales (ISO 15472:2010); Text in English

| Contents | Page |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| Foreword | iv |
| Introduction | v |
| 1 Scope | 1 |
| 2 Normative references | 1 |
| 3 Symbols and abbreviated terms | 1 |
| 4 Outline of method | 2 |
| 5 Procedure for calibrating the energy scale | 5 |
| 5.1 Obtaining the reference samples..... | 5 |
| 5.2 Mounting the samples..... | 6 |
| 5.3 Cleaning the samples..... | 6 |
| 5.4 Choosing the spectrometer settings for which energy calibration is required..... | 6 |
| 5.5 Operating the instrument..... | 6 |
| 5.6 Options for initial or subsequent calibration measurements | 7 |
| 5.7 Measurements for the peak binding-energy repeatability standard deviation and the scale linearity | 7 |
| 5.8 Calculating the peak binding-energy repeatability standard deviation | 8 |
| 5.9 Checking the binding-energy scale linearity | 11 |
| 5.10 Procedure for the regular determination of the calibration error..... | 12 |
| 5.11 Procedures for correction of the instrument binding-energy scale | 13 |
| 5.12 Next calibration..... | 15 |
| 5.13 Establishing the calibration interval..... | 15 |
| Annex A (normative) Least-squares determination of the peak binding energy by a simple computational method | 16 |
| Annex B (informative) Derivation of uncertainties | 19 |
| Annex C (informative) Citation of the uncertainties of measured binding energies | 21 |
| Annex D (informative) Measurements of modified Auger parameters measured using XPS instruments equipped with a monochromated Al X-ray source | 23 |
| Bibliography | 26 |