

# DIN EN 993-10:2020-12 (E)

## Methods of test for dense shaped refractory products - Part 10: Determination of permanent change in dimensions on heating

---

| Contents   | Page |
|--|------|
| European foreword .....  | 3    |
| 1 Scope .....  | 5    |
| 2 Normative references .....   | 5    |
| 3 Terms and definitions .....  | 5    |
| 4 Principle .....  | 6    |
| 5 Apparatus .....  | 6    |
| 6 Test pieces .....  | 7    |
| 7 Procedure .....  | 7    |
| 7.1 Drying of the test pieces .....  | 7    |
| 7.2 Measurement of test pieces .....                                       | 7    |
| 7.2.1 Linear measurement by dial gauge apparatus (Method 1) .....          | 7    |
| 7.2.2 Linear measurement by Vernier callipers (Method 2) .....             | 7    |
| 7.2.3 Volume measurement (Method 3) .....                                  | 8    |
| 7.3 Mounting of test pieces in the furnace .....                           | 8    |
| 7.4 Test temperature .....   | 8    |
| 7.5 Temperature measurement and distribution .....                         | 8    |
| 7.6 Heating .....  | 8    |
| 7.7 Maintenance of test temperature .....                                  | 9    |
| 7.8 Sampling of furnace atmosphere .....                                   | 9    |
| 7.9 Cooling .....  | 9    |
| 7.10 Measurement of test pieces after firing .....                         | 9    |
| 7.10.1 Linear measurement (Methods 1 and 2) .....                          | 9    |
| 7.10.2 Volume measurement (Method 3) .....                                 | 9    |
| 8 Expression of results .....  | 10   |
| 9 Test report .....  | 10   |
| 10 Precision and bias .....  | 11   |
| 10.1 Interlaboratory study .....   | 11   |
| 10.2 Precision data .....  | 11   |
| 10.2.1 Repeatability .....   | 11   |
| 10.2.2 Reproducibility .....   | 11   |
| 10.2.3 Bias .....  | 11   |
| Table 1 -- Permanent change of dimensions on heating .....                 | 11   |
| Figure 1 -- Length-measuring device (method 1) (side view) .....           | 12   |
| Figure 2 -- Test piece carrier (method 1) - (plan view) .....              | 13   |
| Figure 3 -- Measuring points when using Vernier callipers (method 2) ..... | 13   |