

ISO 10863:2020-05 (E)

Non-destructive testing of welds - Ultrasonic testing - Use of time-of-flight diffraction technique (TOFD)

Contents		Page
Foreword		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	2
4	General remarks on the capabilities of the technique	2
5	Testing levels	3
6	Information required prior to testing	4
6.1	Items to be defined by specification	4
6.2	Specific information required by the operator before testing	4
6.3	Written test instruction or procedure	4
7	Requirements for test personnel and test equipment	5
7.1	Personnel qualifications	5
7.2	Test equipment	5
7.2.1	Ultrasonic instrument	5
7.2.2	Ultrasonic probes	5
7.2.3	Scanning mechanisms	5
8	Preparation for testing	5
8.1	Volume to be tested	5
8.2	Setup of probes	6
8.3	Scan increment setting	7
8.4	Geometry considerations	7
8.5	Preparation of scanning surfaces	7
8.6	Temperature	8
8.7	Couplant	8
8.8	Provision of datum points	8
9	Testing of base material	8
10	Range and sensitivity settings	8
10.1	Settings	8
10.1.1	General	8
10.1.2	Time window	8
10.1.3	Time-to-depth conversion	8
10.1.4	Sensitivity settings	9
10.2	Checking of the settings	9
10.3	Reference blocks	9
10.3.1	General	9
10.3.2	Material	9
10.3.3	Dimensions and shape	10
10.3.4	Reference reflectors	10
11	Weld testing	10

12	Interpretation and analysis of TOFD images	11
12.1	General	11
12.2	Assessing the quality of the TOFD image	11
12.3	Identification of relevant TOFD indications	11
12.4	Classification of relevant TOFD indications	11
12.4.1	General	11
12.4.2	TOFD indications from surface-breaking discontinuities	12
12.4.3	TOFD indications from embedded discontinuities	12
12.4.4	Unclassified TOFD indications	13
12.5	Determination of location	13
12.6	Definition and determination of length and height	13
12.6.1	General	13
12.6.2	Determination of length	14
12.6.3	Determination of height	16
12.7	Evaluation against acceptance criteria	17
13	Test report	17
	Annex A (informative) Reference blocks	19
	Annex B (informative) Examples of TOFD scans	24
	Bibliography	37