

# DIN EN ISO 8299:2021-04 (E)

## Nuclear fuel technology - Determination of the isotopic and elemental uranium and plutonium concentrations of nuclear materials in nitric acid solutions by thermal-ionization mass spectrometry (ISO 8299:2019); English version EN ISO 8299:2021

---

<b>Contents</b>		<b>Page</b>
<b>Foreword</b>		<b>v</b>
<b>1</b>	<b>Scope</b>	<b>1</b>
<b>2</b>	<b>Normative references</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions</b>	<b>1</b>
<b>4</b>	<b>Principle</b>	<b>1</b>
<b>5</b>	<b>Reference materials and reagents</b>	<b>2</b>
5.1	Spikes and reference materials	2
5.2	Other chemical reagents	3
5.3	Resin, applicable for separation/purification of Pu and U	4
5.3.1	General	4
5.3.2	Preparation of resin	4
<b>6</b>	<b>Apparatus</b>	<b>5</b>
<b>7</b>	<b>Apparatus for mass spectrometry</b>	<b>6</b>
<b>8</b>	<b>Sample preparation</b>	<b>6</b>
8.1	Subsampling and spiking	6
8.1.1	Pellet or powder samples	7
8.1.2	Concentrated nuclear fuel solution samples (such as reprocessing solution)	7
8.1.3	Plutonium nitrate solution samples (such as product solution from a reprocessing plant)	7
8.1.4	Dried nitrate samples	8
8.2	Chemical valency adjustment	8
8.2.1	Valence adjustment with ferrous solution	8
8.2.2	Valence adjustment with hydrogen peroxide	8
8.3	Sample separation/purification	9
8.3.1	Ion exchange with anion-exchange resin	9
8.3.2	Purification with extraction separation resins (see 5.3.1.2)	10
8.4	Replicate treatments	10
<b>9</b>	<b>Filaments preparation</b>	<b>10</b>
9.1	Degassing of filaments	10
9.2	Sample loading	10
9.2.1	Normal sample loading	10
9.2.2	Graphite loading technique	10
9.2.3	Resin-bead loading on single filaments for Pu samples	11
9.3	Filament mounting (filament assemblies preparation)	11
<b>10</b>	<b>Instrument calibration</b>	<b>11</b>
10.1	Mass calibration	11
10.2	Gain calibration for Faraday multi-detectors	11
10.3	Faraday detector calibration	11
10.4	Mass discrimination calibration	12
<b>11</b>	<b>Isotopic mass spectrometric measurements</b>	<b>12</b>
11.1	Total evaporation measurements using a single or double filament assembly and a multi-Faraday collector system	12
11.2	Bias correction method using a double filament assembly and a multi-Faraday collector system	13

<b>12</b>	<b>Calculation of the results</b> .....	<b>13</b>
12.1	Calculation of ion current intensities.....	13
12.2	Calculation of mean, weighted mean and standard deviation on a set of ratios $x_i$ , ( $i = 1 \dots N$ ).....	14
12.3	Mass discrimination correction.....	14
12.4	Calculation of the atomic percent abundance $A_i$ .....	14
12.5	Calculation of the isotopic mass percent $W_j$ .....	15
12.6	Calculation of concentration.....	15
12.7	Isotope decay correction.....	16
<b>13</b>	<b>Blanks</b> .....	<b>16</b>
<b>14</b>	<b>Quality control</b> .....	<b>16</b>
<b>15</b>	<b>Measurement uncertainty</b> .....	<b>17</b>
15.1	Elemental assay.....	17
15.2	Isotopic analysis.....	17
<b>16</b>	<b>Interferences</b> .....	<b>18</b>
<b>Annex A (normative) Preparation and standardization of spike solutions</b> .....		<b>19</b>
<b>Bibliography</b> .....		<b>25</b>