

# ISO 3892:2000-06 (E)

## Conversion coatings on metallic materials - Determination of coating mass per unit area - Gravimetric methods

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Apparatus .....</b>	<b>1</b>
<b>3</b>	<b>Test pieces .....</b>	<b>2</b>
<b>4</b>	<b>Reagents and procedures .....</b>	<b>2</b>
4.1	General .....	2
4.2	Phosphate coatings on iron and steel .....	2
4.3	Phosphate coatings on zinc and cadmium .....	3
4.4	Crystalline phosphate coatings on aluminium and its alloys .....	3
4.5	Chromate coatings on zinc and cadmium .....	4
4.6	Chromate and amorphous phosphate coatings on aluminium and its alloys .....	4
<b>5</b>	<b>Expression of results .....</b>	<b>5</b>
5.1	Calculation .....	5
5.2	Measurement uncertainty .....	5