

ISO 23737:2021 (E)

Fine ceramics (advanced ceramics, advanced technical ceramics) — Methods for evaluating wear and friction characteristics of fine ceramic thin films under dry and humid conditions

Contents

	Foreword
	Introduction
1	Scope
2	Normative references
3	Terms and definitions
4	Test specimens
5	Measurement principle
6	Testing room environment
7	Wear formation test apparatus
8	Test specimen preparation
9	Test specimen pretreatment
9.1	General
9.2	Test specimen cleaning
9.3	Test specimen drying
10	Environmental conditions for the formation of the wear and the evaluation of friction coefficient
10.1	General
10.2	Dry environment
10.3	High-humidity environment
11	Wear motion conditions
11.1	Reciprocating wear conditions
11.2	Rotating disc wear conditions
12	Evaluation of wear track cross-section formed on thin film test specimen surface
13	Evaluation of volume of worn portion on indenter ball surface
13.1	General
13.2	Observation of indenter ball wear surface profile
13.3	Calculation of volume of worn portion on indenter ball surface
14	Investigations of morphology and elemental distribution maps for wear tracks on thin film test specimens and worn sections on indenter balls
14.1	General
14.2	Observation of the morphology
14.3	Investigations of elemental distribution maps
15	Calculation of friction coefficient
16	Testing procedures

- 16.1 Measurement of thickness of thin film test specimen
- 16.2 Thin film test specimen preparation and cleaning
- 16.3 Setting of wear formation conditions
 - 16.3.1 General
 - 16.3.2 Wear formation conditions for a dry environment
 - 16.3.3 Wear formation conditions for a high-humidity environment
- 16.4 Wear formation
 - 16.4.1 Start of wear formation on the thin film test specimen
 - 16.4.2 Friction force measurement
- 16.5 Evaluation of thin film test specimen surface and indenter ball surface after wear formation
 - 16.5.1 General
 - 16.5.2 Measurement of wear track cross-section on thin film test specimen
 - 16.5.3 Evaluation of volume of worn portion on indenter ball surface
 - 16.5.4 Investigations of morphology and elemental distribution maps
- 16.6 Calculation of friction coefficient
- 17 Precautions for summarization of test results
- 18 Test report
- Annex A (informative) Example of reciprocating slide wear results and rotating slide wear results
 - A.1 Difference between reciprocating slide wear results and rotating slide wear results
 - A.2 Example of reciprocating slide wear results and rotating slide wear results
- Annex B (informative) Method of holding polymer film or thin glass plate with a thickness of < 200 μm in sliding wear formations
 - B.1 Necessity to consider a method of holding film or thin glass plate substrates with a thickness of < 200 μm in sliding wear formations
 - B.2 Example of a holding method using a vacuum chuck plate
 - B.3 Results of a reciprocating sliding wear formation for an ITO thin film deposited on a PET film under humid conditions
- Annex C (informative) Effects of combining thin film materials and indenter materials in sliding wear tests
 - C.1 Necessity to examine the combination of a thin film material and an indenter ball material
 - C.2 Summary of some results of an investigation into combining a thin film material and an indenter ball material
- Annex D (informative) Investigation of optimal load for indenter
 - D.1 Necessity to optimize the test indenter load
 - D.2 Relationship between the indenter load and the maximum wear track depth
 - D.3 Criteria for selecting the indenter load and the number of strokes
- Annex E (informative) Quantification of wear track cross-section area
- Annex F (informative) Examples of investigations of morphology and elemental distribution maps for wear tracks on thin films and worn sections of indenter balls
 - F.1 Necessity to investigate the morphology of wear tracks and indenter ball surfaces and perform elemental analysis of wear tracks and indenter ball surfaces
 - F.2 Examples of observations of the wear tracks and indenter ball surface morphology and elemental distribution