

DIN EN ISO 105-B04:2024-06 (E)

Textiles - Tests for colour fastness - Part B04: Colour fastness to artificial weathering: Xenon arc fading lamp test (ISO 105-B04:2024)

Contents		Page
European foreword.....		3
Foreword.....		4
Introduction.....		5
1	Scope	6
2	Normative references	6
3	Terms and definitions	6
4	Principle	7
5	Materials	7
5.1	Blue wool references.....	7
5.2	Glass case for blue wool references.....	7
5.3	Specimen mounting cards.....	7
5.4	Specimen covers.....	7
5.5	Specimen holders.....	7
5.6	Grey scale for assessing change in colour.....	7
6	Apparatus	8
6.1	Laboratory light source.....	8
6.1.1	General.....	8
6.1.2	Spectral irradiance.....	8
6.2	Test chamber.....	9
6.3	Radiometer.....	10
6.4	Temperature sensors.....	10
6.4.1	General.....	10
6.4.2	Chamber air temperature thermometer.....	10
6.4.3	Black-standard thermometer (BST) and black-panel thermometer (BPT).....	10
7	Exposure conditions	10
7.1	General.....	10
7.2	Exposure of test specimens.....	10
7.3	Exposure of colour fastness references.....	11
8	Test specimens	11
9	Procedure	11
9.1	General.....	11
9.2	Exposure methods.....	12
9.2.1	General.....	12
9.2.2	Method 1.....	12
9.2.3	Method 2.....	12
9.2.4	Method 3.....	13
9.3	Drying.....	13
9.4	Mounting for assessment.....	13
10	Assessment of colour fastness to weathering	13
11	Test report	14
Annex A (informative) General information on colour fastness to light		15
Annex B (informative) Radiometer for controlling exposure duration		17
Bibliography		18