

DIN EN ISO 105-B04:2024-06 (E)

Textiles - Tests for colour fastness - Part B04: Colour fastness to artificial weathering: Xenon arc fading lamp test (ISO 105-B04:2024)

Contents		Page
European foreword		3
Foreword		4
Introduction		5
1 Scope		6
2 Normative references		6
3 Terms and definitions		6
4 Principle		7
5 Materials		7
5.1	Blue wool references	7
5.2	Glass case for blue wool references	7
5.3	Specimen mounting cards	7
5.4	Specimen covers	7
5.5	Specimen holders	7
5.6	Grey scale for assessing change in colour	7
6 Apparatus		8
6.1	Laboratory light source	8
6.1.1	General	8
6.1.2	Spectral irradiance	8
6.2	Test chamber	9
6.3	Radiometer	10
6.4	Temperature sensors	10
6.4.1	General	10
6.4.2	Chamber air temperature thermometer	10
6.4.3	Black-standard thermometer (BST) and black-panel thermometer (BPT)	10
7 Exposure conditions		10
7.1	General	10
7.2	Exposure of test specimens	10
7.3	Exposure of colour fastness references	11
8 Test specimens		11
9 Procedure		11
9.1	General	11
9.2	Exposure methods	12
9.2.1	General	12
9.2.2	Method 1	12
9.2.3	Method 2	12
9.2.4	Method 3	13
9.3	Drying	13
9.4	Mounting for assessment	13
10 Assessment of colour fastness to weathering		13
11 Test report		14
Annex A (informative) General information on colour fastness to light		15
Annex B (informative) Radiometer for controlling exposure duration		17
Bibliography		18