

DIN 51007-1:2024-08 (E)

Thermal analysis (TA) - Differential thermal analysis (DTA) and differential scanning calorimetry (DSC) - Part 1: General Principles

Contents	Page
Foreword	4
1 Scope	6
2 Normative references	6
3 Terms and definitions.....	6
4 Principle of methods.....	6
4.1 General	6
4.2 Differential thermal analysis (DTA) and heat-flux differential scanning calorimetry (hf-DSC)	7
4.3 Power compensation differential scanning calorimetry (pc-DSC).....	7
5 Apparatus	7
5.1 General	7
5.2 Oven.....	8
5.3 Temperature control	8
5.4 Apparatus for generating a defined atmosphere.....	8
5.5 Control, data recording and data evaluation devices.....	9
5.6 Analytical balance or microbalance.....	9
5.7 Sample container.....	9
6 Calibration.....	9
6.1 General	9
6.2 Calibration substances	10
6.3 Temperature calibration	11
6.4 Heat calibration	12
6.5 Heat capacity calibration	12
7 Objectives of the investigation.....	14
7.1 Determination of characteristic temperatures and heat of transition.....	14
7.1.1 First order phase transitions.....	14
7.1.2 Chemical reactions.....	18
7.1.3 Glass transition	19
7.2 Determination of heat capacities.....	23
7.3 Determination of eutectic purity.....	24
7.4 Other investigation aims.....	26
8 Sampling.....	26
9 Sample preparation.....	27
10 Setting up the apparatus.....	27
11 Test report.....	28
Bibliography.....	30

Figures

Figure 1 — Endothermic peak — Characteristic temperatures or times and types of baseline construction upon heating involving a first order phase transition.....	16
--	----

Figure 2 — Exothermic peak — Characteristic temperatures or times and types of baseline construction upon cooling involving a first order phase transition	17
Figure 3 — Endothermic peak — Construction of a baseline with a point of inflection (option b).....	18
Figure 4 — Characteristic temperatures and types of baselines for an exothermic peak of a chemical reaction	19
Figure 5 — DSC curve for a sample with glass transition.....	20
Figure 6 — Determination of the glass transition temperature T_g based on the function $H = H(T)$ of a glass transition with enthalpy relaxation.....	21
Figure 7 — Determination of the glass transition temperature based on the heat capacity function $C_p = C_p(T)$ of a glass transition with enthalpy relaxation.....	22
Figure 8 — Determination of the glass transition temperature based on the heat capacity function $C_p = C_p(T)$ of a glass transition without enthalpy relaxation	23
Figure 9 — Determination of heat capacity using two DSC measurements	24
Figure 10 — van't Hoff diagram for determination of eutectic purity (example).....	26

Tables

Table 1 — Typical temperature ranges	8
Table 2 — Recommended calibration substances	10
Table 3 — Specific heat capacity c_p of synthetic corundum ($\alpha\text{-Al}_2\text{O}_3$, “sapphire”) [3] [4]	13
Table 4 — Polynomial coefficients for calculating the molar heat capacity of corundum ($\alpha\text{-Al}_2\text{O}_3$, “sapphire”, molar mass $M = 101,961\ 3\ \text{g mol}^{-1}$) [3] [4].....	14