

# ISO 9717:2024-07 (E)

## Metallic and other inorganic coatings - Phosphate conversion coating of metals

<b>Contents</b>	<b>Page</b>
Foreword.....	iv
Introduction.....	vi
<b>1 Scope</b> .....	<b>1</b>
<b>2 Normative references</b> .....	<b>1</b>
<b>3 Terms and definitions</b> .....	<b>1</b>
<b>4 Information to be supplied by the purchaser to the processor</b> .....	<b>1</b>
<b>5 Coating types and their importance</b> .....	<b>2</b>
5.1 Coating types.....	2
5.2 Designation of phosphate conversion coating.....	2
5.3 Example for designation of phosphate conversion coating.....	3
<b>6 Requirements</b> .....	<b>3</b>
6.1 Appearance.....	3
6.2 Coating mass per unit area.....	3
6.3 Post treatment.....	3
6.4 Correlation of coating thickness and area related mass.....	4
<b>7 Heat treatment</b> .....	<b>4</b>
<b>Annex A (normative) Determination of phosphate conversion coating resistance to neutral salt spray test</b> .....	<b>5</b>
<b>Annex B (informative) General information</b> .....	<b>8</b>
<b>Annex C (informative) Identification of phosphate conversion coating</b> .....	<b>11</b>
<b>Bibliography</b> .....	<b>13</b>