

# DIN CEN/TS 18094:2025-02 (E)

Non-destructive testing - Test method for determining residual stresses by synchrotron x-ray diffraction; English version CEN/TS 18094:2024

---

<b>Contents</b>		<b>Page</b>
European foreword .....		4
Introduction .....		5
1	Scope.....	6
2	Normative references.....	6
3	Terms and definitions .....	6
4	Symbols and abbreviated terms.....	11
4.1	Symbols and units.....	11
4.2	Subscripts .....	12
4.3	Abbreviations.....	12
5	Summary of the synchrotron XRD measurement method.....	12
5.1	General.....	12
5.2	Diffraction techniques.....	14
5.2.1	General information .....	14
5.2.2	Effects due to the material structure .....	15
5.3	Synchrotron high energy X-ray diffraction.....	16
5.3.1	General.....	16
5.3.2	Monochromatic beam for angle-dispersive X-ray diffraction (ADXRD) .....	16
5.3.3	Polychromatic beam for energy-dispersive X-ray diffraction (EDXRD) .....	17
5.4	Residual stress calculation.....	17
5.4.1	Strain .....	17
5.4.2	Stress .....	19
5.5	Sources of error and uncertainty .....	21
5.5.1	Errors and misapplications.....	21
5.5.2	Uncertainties .....	22
6	Preparation of measurement and calibration.....	23
6.1	Sample preparation .....	23
6.1.1	General.....	23
6.1.2	Geometry.....	23
6.1.3	Composition.....	23
6.1.4	Thermal/mechanical history.....	24
6.1.5	Phases and crystals .....	24
6.1.6	Homogeneity, microstructure and texture.....	24
6.1.7	Grain size .....	24
6.2	Instrumentation preparation.....	24
6.2.1	Instrumentation calibration .....	24
6.2.2	Verification of the instrumentation .....	24
6.3	Experimental setup .....	25
6.3.1	Choosing the measurement method and beam type.....	25
6.3.2	Reflection geometry.....	25
6.3.3	Transmission geometry.....	25
6.3.4	Energy-dispersive (EDXRD) mode.....	25
6.3.5	Angle dispersive (ADXRD) mode.....	25
6.3.6	Determination of the gauge volume (GV).....	26
6.3.7	Peak selection .....	26

6.3.8	Temperature .....	27
6.4	Measurement procedure: EDXRD – transmission.....	27
6.4.1	General considerations .....	27
6.4.2	Calibration of the detector .....	27
6.4.3	Instrument alignment.....	27
6.4.4	Calibration of scattering angle.....	27
6.5	Measurement procedure: EDXRD – reflection .....	28
6.5.1	General considerations .....	28
6.5.2	Calibration of detector.....	28
6.5.3	Instrument alignment.....	28
6.5.4	Calibration of scattering angle.....	28
6.5.5	Determination of gauge volume (GV).....	28
6.5.6	Sample positioning.....	29
6.5.7	Slit positioning.....	29
6.6	Measurement procedure: ADXRD – transmission and reflection .....	29
6.6.1	General considerations .....	29
6.6.2	Calibration of detector.....	29
6.6.3	Instrument alignment.....	30
6.6.4	Calibration of scattering angle.....	30
6.6.5	Detector distance.....	30
6.6.6	Defining beam parameters.....	30
6.6.7	Performing the measurement.....	31
6.7	Measurement procedure: ADXRD – CSC .....	31
6.7.1	General considerations .....	31
6.7.2	Calibration of detector.....	31
6.7.3	Instrument alignment.....	31
7	Measurement and recording requirements .....	31
7.1	General .....	31
7.2	Measurements .....	31
7.3	Recording requirements.....	32
7.4	Reduction of measurement data and data fitting .....	32
8	Data analysis and stress calculation .....	33
8.1	Specific equations for synchrotron radiation-based diffraction techniques.....	33
8.1.1	General .....	33
8.1.2	Data input.....	33
8.1.3	Stress-free reference input .....	34
8.1.4	Strain calculation.....	34
8.1.5	Elastic constant input.....	34
8.1.6	Stress calculation.....	34
8.2	Evaluation of uncertainty in the measurement.....	35
8.2.1	Random and systematic uncertainties .....	35
8.2.2	Interlaboratory comparison.....	36
8.3	Description of the final residual stress data output format.....	36
9	Reporting.....	37
Annex A (informative)	Reference samples.....	38
Annex B (informative)	Harmonization of data structures.....	41
Bibliography	.....	47