

ISO 15472:2001-02 (E)

Surface chemical analysis - X-ray photoelectron spectrometers - Calibration of energy scales

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative reference	1
3	Symbols and abbreviated terms	1
4	Outline of method	2
5	Procedure for calibrating the energy scale	6
5.1	Obtaining the reference samples	6
5.2	Mounting the samples	6
5.3	Cleaning the samples	6
5.4	Choosing the spectrometer settings for which energy calibration is required	6
5.5	Operating the instrument	6
5.6	Options for initial or subsequent calibration measurements	7
5.7	Measurements for the peak binding-energy repeatability standard deviation and the scale linearity	7
5.8	Calculating the peak binding-energy repeatability standard deviation	8
5.9	Checking the binding-energy scale linearity	11
5.10	Procedure for the regular determination of the calibration error	12
5.11	Procedures for correction of the instrument binding-energy scale	13
5.12	Next calibration	15
5.13	Establishing the calibration interval	15
Annex A (normative)	Least-squares determination of the peak binding energy by a simple computational method	16
Annex B (informative)	Derivation of uncertainties	19
Annex C (informative)	Citation of the uncertainties of measured binding energies	21
Annex D (informative)	Measurements of modified Auger parameters measured using XPS instruments equipped with a monochromated Al X-ray source	23
Bibliography		26