

# ISO 17974:2002-10 (E)

## Surface chemical analysis - High-resolution Auger electron spectrometers - Calibration of energy scales for elemental and chemical-state analysis

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative reference .....	1
3	Terms and definitions .....	1
4	Symbols and abbreviated terms .....	2
5	Outline of method .....	3
6	Procedure for calibrating the energy scale .....	6
6.1	Obtaining reference samples .....	6
6.2	Mounting samples .....	6
6.3	Cleaning samples .....	6
6.4	Choosing spectrometer settings for energy calibration .....	6
6.5	Operating the instrument .....	7
6.6	Options for initial or subsequent calibration measurements .....	7
6.7	Measurements for peak kinetic energy repeatability standard deviation and scale linearity .....	8
6.8	Calculating peak kinetic energy repeatability standard deviation .....	10
6.9	Determining relevant reference kinetic energies .....	12
6.10	Checking kinetic energy scale linearity .....	13
6.11	Procedure for regular calibration error determination .....	14
6.12	Procedures for correction of the instrument kinetic energy scale .....	15
6.13	Next calibration .....	17
6.14	Establishing calibration intervals .....	17
Annex A (normative)	Maximum number of points for a single application of Savitzky and Golay smoothing of peaks at 0,1 eV energy intervals .....	19
Annex B (normative)	Least squares determination of peak kinetic energy by a simple computational method .....	20
Annex C (informative)	Derivation of uncertainties .....	23
Annex D (informative)	Citation of uncertainties of measured kinetic energies .....	25
Bibliography .....		27