

# ISO 19318:2004-05 (E)

## Surface chemical analysis - X-ray photoelectron spectroscopy - Reporting of methods used for charge control and charge correction

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative reference .....	1
3	Terms and definitions .....	1
4	Symbols and abbreviated terms .....	1
5	Apparatus .....	2
6	Calibration of binding-energy scale .....	2
7	Reporting of information related to charge control .....	2
7.1	Methods of charge control .....	2
7.2	Information on specimen .....	2
7.3	Instrument and operating conditions .....	3
7.4	General method for charge control .....	3
7.5	Reasons for needing charge control and for choosing the particular method for charge control .....	3
7.6	Values of experimental parameters .....	3
7.7	Information on the effectiveness of the method of charge control .....	4
8	Reporting of method(s) used for charge correction and the value of that correction .....	4
8.1	Methods of charge correction .....	4
8.2	Approach .....	4
8.3	Value of correction energy .....	4
Annex A (informative) Description of methods of charge control and charge correction .....		5
A.1	Introduction .....	5
A.2	Methods of charge control .....	5
A.3	Methods of charge correction .....	7
A.4	Bias referencing [17] .....	8
A.5	Auger parameter measurements [32-34] .....	9
Bibliography .....		10