

ISO 21270:2004-06 (E)

Surface chemical analysis - X-ray photoelectron and Auger electron spectrometers - Linearity of intensity scale

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative reference	1
3	Symbols	1
4	Outline of the methods	2
5	When to use this International Standard	2
6	Procedure for evaluating the intensity linearity	2
6.1	The samples	2
6.2	Preparing the copper sample	3
6.3	Preparing the stainless-steel sample or sample holder	3
6.4	Choosing the spectrometer settings for which the intensity linearity measurement is required	3
6.5	Operating the instrument	3
6.6	Measurement of the intensity scale linearity by varying the source flux	4
6.7	Determination of the intensity scale linearity by varying the source flux	4
6.8	Measurement of the intensity scale linearity in XPS using the spectrum ratio method for systems with two or more but less than 30 X-ray source emission current settings	6
6.9	Determination of the intensity scale linearity in XPS using the spectrum ratio method for systems with two or more but less than 30 X-ray source emission current settings	7
6.10	Completing the analysis	9
Annex A (informative)	Example results of linearity measurements using the spectrum ratio method (the second method)	10
Bibliography		13