

ISO/TS 21432:2005-07 (E)

Non-destructive testing - Standard test method for determining residual stresses by neutron diffraction

Contents		Page
Foreword		v
Introduction		vi
1	Scope	1
2	Normative references	1
3	Terms and definitions	2
4	Symbols and abbreviated terms	5
4.1	Symbols	5
4.2	Subscripts	6
4.3	Abbreviated terms	7
5	Summary of method	7
5.1	Preamble	7
5.2	Outline of principle -- Bragg's law	7
5.3	Neutron sources	7
5.4	Strain measurement	7
5.5	Neutron diffractometers	8
5.6	Stress determination	9
6	Preparations for measurements	12
6.1	Preamble	12
6.2	Alignment and calibration of the instrument	12
6.3	Choice of diffraction conditions	12
6.3.1	Monochromatic instruments	12
6.3.2	TOF instruments	15
6.4	Positioning procedures	15
6.5	Gauge volumes	15
6.6	Determination of a strain free or reference lattice spacing	16
7	Material characterization	18
7.1	Preamble	18
7.2	Composition	18
7.3	Thermal/mechanical history	18
7.4	Phases and crystal structures	18
7.5	Homogeneity	18
7.6	Microstructure	18
7.7	Texture	18
8	Recording requirements and measurement procedure	19
8.1	Preamble	19
8.2	Recording requirements	19
8.2.1	General information -- instrument	19
8.2.2	General information -- specimen	20
8.2.3	Specific information required for each strain measurement	20
8.3	Specimen co-ordinates	21
8.4	Positioning of the specimen	21
8.5	Measurement directions	21

8.6	Number and location of measuring positions	21
8.7	Gauge volume	21
8.8	Gauge volume centroid considerations	21
8.9	Temperature	22
9	Calculation of stress	22
9.1	Preamble	22
9.2	Normal stress determinations	22
9.3	Stress state determinations	23
9.3.1	The sin ² method	23
9.4	Choice of elasticity constants	23
9.5	Data analysis	24
9.5.1	Peak fitting function	24
9.5.2	Background function	24
9.5.3	Peak to background ratio	24
9.5.4	Distorted peak profiles	24
10	Reliability of results	25
11	Reporting	25
11.1	Preamble	25
11.2	Strain or stress values	25
11.2.1	Stress free or reference lattice spacing	26
11.2.2	Conversion of strain to stress	26
11.2.3	Elasticity constants	26
11.2.4	Positioning	26
11.3	Neutron source and instrument	26
11.4	General measurement procedures	26
11.5	Specimens/materials properties	26
11.6	Original data	27
	Annex A (informative) Measurement procedures	28
	Annex B (informative) Determination of uncertainties in a measurand	36
	Bibliography	39