

# ISO 1099:2006-04 (E)

## Metallic materials - Fatigue testing - Axial force-controlled method

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Test plan .....	3
4.1	General outline .....	3
4.2	Presentation of fatigue results .....	4
4.2.1	Wöhler or S-N curve .....	4
4.2.2	Mean stress diagrams .....	4
4.2.3	Alignment .....	4
5	Shape and size of specimen .....	5
5.1	Form of specimens .....	5
5.2	Specimen temperature measurement .....	5
6	Specimens .....	6
6.1	Geometry .....	6
6.1.1	Products (bars, flat sheets over 5 mm thick) .....	6
6.1.2	Flat products with thickness of 5 mm or less .....	6
6.2	Preparation of specimens .....	7
6.2.1	Machining procedure .....	7
6.2.2	Sampling and marking .....	7
6.2.3	Surface condition of the specimen .....	8
6.2.4	Dimensional checks .....	8
6.2.5	Storage and handling .....	8
7	Apparatus .....	8
7.1	Testing machine .....	8
7.1.1	Force transducer .....	9
7.1.2	Gripping of specimen .....	9
7.1.3	Alignment check .....	9
7.2	Instrumentation for test monitoring .....	9
7.2.1	Recording systems .....	9
7.2.2	Cycle counter .....	9
7.3	Checking and verification .....	10
8	Testing machine .....	10
9	Mounting of specimen .....	10
10	Speed of testing .....	10
11	Application of force .....	11
12	Recording of temperature and humidity .....	11

<b>13</b>	<b>Criterion of failure and test termination .....</b>	<b>11</b>
<b>13.1</b>	<b>Criterion of failure .....</b>	<b>11</b>
<b>13.2</b>	<b>Test termination .....</b>	<b>11</b>
<b>14</b>	<b>Test report .....</b>	<b>12</b>
	<b>Bibliography .....</b>	<b>21</b>