

ISO 1099:2006-04 (E)

Metallic materials - Fatigue testing - Axial force-controlled method

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Test plan	3
4.1	General outline	3
4.2	Presentation of fatigue results	4
4.2.1	Wöhler or S-N curve	4
4.2.2	Mean stress diagrams	4
4.2.3	Alignment	4
5	Shape and size of specimen	5
5.1	Form of specimens	5
5.2	Specimen temperature measurement	5
6	Specimens	6
6.1	Geometry	6
6.1.1	Products (bars, flat sheets over 5 mm thick)	6
6.1.2	Flat products with thickness of 5 mm or less	6
6.2	Preparation of specimens	7
6.2.1	Machining procedure	7
6.2.2	Sampling and marking	7
6.2.3	Surface condition of the specimen	8
6.2.4	Dimensional checks	8
6.2.5	Storage and handling	8
7	Apparatus	8
7.1	Testing machine	8
7.1.1	Force transducer	9
7.1.2	Gripping of specimen	9
7.1.3	Alignment check	9
7.2	Instrumentation for test monitoring	9
7.2.1	Recording systems	9
7.2.2	Cycle counter	9
7.3	Checking and verification	10
8	Testing machine	10
9	Mounting of specimen	10
10	Speed of testing	10
11	Application of force	11
12	Recording of temperature and humidity	11

13	Criterion of failure and test termination	11
13.1	Criterion of failure	11
13.2	Test termination	11
14	Test report	12
	Bibliography	21