

ISO 20903:2006-07 (E)

Surface chemical analysis - Auger electron spectroscopy and X-ray photoelectron spectroscopy - Methods used to determine peak intensities and information required when reporting results

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Symbols and abbreviated terms	1
5	Methods for peak-intensity determination -- Direct spectrum	2
5.1	General	2
5.2	Selection and subtraction of an inelastic background	3
5.3	Measurement of peak intensity	4
5.3.1	Measurement of peak height	4
5.3.2	Measurement of peak area	4
5.4	Measurement of a peak intensity with computer software	5
5.5	Measurement of peak intensities for a spectrum with overlapping peaks	5
5.6	Uncertainty in measurement of peak area	6
6	Methods for peak intensity determination -- Auger-electron differential spectrum	6
6.1	General	6
6.2	Measurement of Auger-electron differential intensity	7
6.3	Uncertainties in measurement of Auger-electron differential intensity	7
7	Reporting of methods used to measure peak intensities	8
7.1	General requirements	8
7.2	Methods used to determine peak intensities in direct spectra	8
7.2.1	Intensity measurement for a single peak, as described in 5.2 and 5.3	8
7.2.2	Intensity measurements from peak fitting, as described in 5.4 and 5.5	9
7.3	Methods used to obtain and determine peak intensities in Auger-electron differential spectra	9
7.3.1	Method used to obtain differential spectra	9
7.3.2	Method used to determine peak intensities, as described in 6.2	9
Annex A (informative)	Instrumental effects on measured intensities	10
Bibliography		11