

# ISO 5636-4:2013-11 (E)

## Paper and board - Determination of air permeance (medium range) - Part 4: Sheffield method

---

<b>Contents</b>		<b>Page</b>
<b>Foreword</b> .....		<b>iv</b>
<b>1</b>	<b>Scope</b> .....	<b>1</b>
<b>2</b>	<b>Normative references</b> .....	<b>1</b>
<b>3</b>	<b>Terms and definitions</b> .....	<b>1</b>
<b>4</b>	<b>Principle</b> .....	<b>1</b>
<b>5</b>	<b>Apparatus</b> .....	<b>2</b>
<b>6</b>	<b>Sampling</b> .....	<b>3</b>
<b>7</b>	<b>Conditioning</b> .....	<b>3</b>
<b>8</b>	<b>Preparation of test pieces</b> .....	<b>3</b>
<b>9</b>	<b>Calibration</b> .....	<b>4</b>
<b>9.1</b>	<b>Variable-area flow-measuring device</b> .....	<b>4</b>
<b>9.2</b>	<b>Electronic flow-measuring device</b> .....	<b>4</b>
<b>10</b>	<b>Procedure</b> .....	<b>4</b>
<b>11</b>	<b>Expression of results</b> .....	<b>4</b>
<b>11.1</b>	<b>Calculation of air permeance</b> .....	<b>4</b>
<b>11.2</b>	<b>Reporting the results</b> .....	<b>5</b>
<b>11.3</b>	<b>Standard deviation and coefficient of variation</b> .....	<b>5</b>
<b>12</b>	<b>Test report</b> .....	<b>5</b>
<b>Annex A (normative) Calibration of flowmeters</b> .....		<b>6</b>
<b>Annex B (informative) Conversion of Sheffield units (SU) to SI units</b> .....		<b>10</b>
<b>Annex C (informative) Precision data</b> .....		<b>11</b>
<b>Bibliography</b> .....		<b>13</b>