

# ISO 7870-2:2013-04 (E)

## Control charts - Part 2: Shewhart control charts

---

<b>Contents</b>		Page
<b>Foreword</b> .....		<b>iv</b>
<b>Introduction</b> .....		<b>v</b>
<b>1 Scope</b> .....		<b>1</b>
<b>2 Normative references</b> .....		<b>1</b>
<b>3 Terms, definitions and symbols</b> .....		<b>1</b>
3.1 General .....		1
3.2 Symbols .....		1
<b>4 Nature of Shewhart control charts</b> .....		<b>3</b>
<b>5 Types of control charts</b> .....		<b>5</b>
5.1 Control charts where no pre-specified values are given .....		5
5.2 Control charts with respect to given pre-specified values .....		6
5.3 Types of variables and attributes control charts .....		6
<b>6 Variables control charts</b> .....		<b>7</b>
6.1 Mean ( $\bar{X}$ ) chart and range ( $R$ ) chart or mean ( $\bar{X}$ ) chart and standard deviation ( $s$ ) chart .....		8
6.2 Control chart for individuals ( $X$ ) and control chart for moving ranges ( $R_m$ ) .....		9
6.3 Control charts for medians ( $\tilde{X}$ ) .....		10
<b>7 Control procedure and interpretation for variables control charts</b> .....		<b>11</b>
7.1 Collect preliminary data .....		11
7.2 Examine the $s$ (or $R$ ) chart .....		11
7.3 Remove assignable causes and revise the chart .....		11
7.4 Examine the $X$ chart .....		12
7.5 Ongoing monitoring of process .....		12
<b>8 Pattern tests for assignable causes of variation</b> .....		<b>12</b>
<b>9 Process control, process capability, and process improvement</b> .....		<b>13</b>
<b>10 Attributes control charts</b> .....		<b>15</b>
<b>11 Preliminary considerations before starting a control chart</b> .....		<b>17</b>
11.1 Choice of critical to quality (CTQ) characteristics describing the process to control .....		17
11.2 Analysis of the process .....		17
11.3 Choice of rational subgroups .....		17
11.4 Frequency and size of subgroups .....		18
11.5 Preliminary data collection .....		18
11.6 Out of control action plan .....		18
<b>12 Steps in the construction of control charts</b> .....		<b>18</b>
12.1 Determine data collection strategy .....		19
12.2 Data collection and computation .....		20
12.3 Plotting $\bar{X}$ chart and $R$ chart .....		20
<b>13 Caution with Shewhart control charts</b> .....		<b>20</b>
13.1 General caution .....		21
13.2 Correlated data .....		22
13.3 Use of alternative rule to the three-sigma rule .....		22
<b>Annex A (informative) Illustrative examples</b> .....		<b>24</b>
<b>Annex B (informative) Practical notices on the pattern tests for assignable causes of variation</b> .....		<b>42</b>
<b>Bibliography</b> .....		<b>44</b>