

# ISO 11095:1996-02 (E)

## Linear calibration using reference materials

---

<b>Contents</b>		<b>Page</b>
1	Scope .....	1
2	Normative references .....	1
3	Definitions .....	1
4	General principles .....	2
5	Basic method .....	2
6	The steps of the basic method.....	4
7	Control method.....	10
8	Two alternatives to the basic method .....	13
9	Example .....	16
<b>Annexes</b>		
A	List of symbols and abbreviations.....	25
B	Basic method when the number of replicates is not constant .....	27
C	Bibliography .....	29