

ISO 11095:1996-02 (E)

Linear calibration using reference materials

Contents		Page
1	Scope	1
2	Normative references	1
3	Definitions	1
4	General principles	2
5	Basic method	2
6	The steps of the basic method.....	4
7	Control method.....	10
8	Two alternatives to the basic method	13
9	Example	16
Annexes		
A	List of symbols and abbreviations.....	25
B	Basic method when the number of replicates is not constant	27
C	Bibliography	29