

ISO 7870-8:2017-04 (E)

Control charts - Part 8: Charting techniques for short runs and small mixed batches

Contents		Page
Foreword		v
Introduction		vi
1	Scope	1
2	Normative references	1
3	Terms, definitions and symbols	1
3.1	Terms and definitions	1
3.2	Symbols	1
4	How to select the correct type of Shewhart control chart for continuous variables data	2
4.1	General	2
4.2	How to select the correct type of Shewhart control chart for measured data generally	2
4.3	How to select the Shewhart control chart when the characteristic does not have a constant aim or process spread	3
5	How to prepare for short run, small mixed batch control charting	5
5.1	Focus on the process	5
5.2	Procedure for grouping similar processes	5
5.3	Typical applications	7
5.4	Preliminary process diagnosis	8
5.5	Procedure to establish the correct initial set-up of a process characteristic	8
5.5.1	Purpose	8
5.5.2	Scope and limitations	8
5.5.3	Reasons for need of procedure	8
5.5.4	Method	9
5.5.5	Example	10
5.6	Procedure to pre-establish control limits for SPC charts for short run, small batch, processes	11
5.6.1	Purpose	11
5.6.2	Scope of application	11
5.6.3	Reasons for need of procedure	11
5.6.4	Method	11
5.6.5	Example	12
6	How to establish and apply short run, small mixed batch, control charts	15
6.1	General	15
6.2	Variable aim, individual and moving range chart	15
6.2.1	Purpose	15
6.2.2	Scope of application	16
6.2.3	Method	16
6.2.4	Example	16
6.3	Variable aim, moving mean and moving range chart	18
6.3.1	Purpose	18
6.3.2	Scope of application	18
6.3.3	Method	18
6.3.4	Example	19
6.4	Universal, individual and moving range chart	20
6.4.1	Purpose	20
6.4.2	Scope of application	20

6.4.3	Method	20
6.4.4	Example	21
6.5	Universal, moving mean and moving range chart	22
6.5.1	Purpose	22
6.5.2	Scope of application	23
6.5.3	Method	23
6.5.4	Example	24
Annex A (informative) Reproducible copies of control charts forms and normal probability worksheet		25
Bibliography		31