

# ISO 7870-8:2017-04 (E)

## Control charts - Part 8: Charting techniques for short runs and small mixed batches

---

<b>Contents</b>		<b>Page</b>
Foreword .....		v
Introduction .....		vi
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms, definitions and symbols .....</b>	<b>1</b>
<b>3.1</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>3.2</b>	<b>Symbols .....</b>	<b>1</b>
<b>4</b>	<b>How to select the correct type of Shewhart control chart for continuous variables data .....</b>	<b>2</b>
<b>4.1</b>	<b>General .....</b>	<b>2</b>
<b>4.2</b>	<b>How to select the correct type of Shewhart control chart for measured data generally .....</b>	<b>2</b>
<b>4.3</b>	<b>How to select the Shewhart control chart when the characteristic does not have a constant aim or process spread .....</b>	<b>3</b>
<b>5</b>	<b>How to prepare for short run, small mixed batch control charting .....</b>	<b>5</b>
<b>5.1</b>	<b>Focus on the process .....</b>	<b>5</b>
<b>5.2</b>	<b>Procedure for grouping similar processes .....</b>	<b>5</b>
<b>5.3</b>	<b>Typical applications .....</b>	<b>7</b>
<b>5.4</b>	<b>Preliminary process diagnosis .....</b>	<b>8</b>
<b>5.5</b>	<b>Procedure to establish the correct initial set-up of a process characteristic .....</b>	<b>8</b>
<b>5.5.1</b>	<b>Purpose .....</b>	<b>8</b>
<b>5.5.2</b>	<b>Scope and limitations .....</b>	<b>8</b>
<b>5.5.3</b>	<b>Reasons for need of procedure .....</b>	<b>8</b>
<b>5.5.4</b>	<b>Method .....</b>	<b>9</b>
<b>5.5.5</b>	<b>Example .....</b>	<b>10</b>
<b>5.6</b>	<b>Procedure to pre-establish control limits for SPC charts for short run, small batch, processes .....</b>	<b>11</b>
<b>5.6.1</b>	<b>Purpose .....</b>	<b>11</b>
<b>5.6.2</b>	<b>Scope of application .....</b>	<b>11</b>
<b>5.6.3</b>	<b>Reasons for need of procedure .....</b>	<b>11</b>
<b>5.6.4</b>	<b>Method .....</b>	<b>11</b>
<b>5.6.5</b>	<b>Example .....</b>	<b>12</b>
<b>6</b>	<b>How to establish and apply short run, small mixed batch, control charts .....</b>	<b>15</b>
<b>6.1</b>	<b>General .....</b>	<b>15</b>
<b>6.2</b>	<b>Variable aim, individual and moving range chart .....</b>	<b>15</b>
<b>6.2.1</b>	<b>Purpose .....</b>	<b>15</b>
<b>6.2.2</b>	<b>Scope of application .....</b>	<b>16</b>
<b>6.2.3</b>	<b>Method .....</b>	<b>16</b>
<b>6.2.4</b>	<b>Example .....</b>	<b>16</b>
<b>6.3</b>	<b>Variable aim, moving mean and moving range chart .....</b>	<b>18</b>
<b>6.3.1</b>	<b>Purpose .....</b>	<b>18</b>
<b>6.3.2</b>	<b>Scope of application .....</b>	<b>18</b>
<b>6.3.3</b>	<b>Method .....</b>	<b>18</b>
<b>6.3.4</b>	<b>Example .....</b>	<b>19</b>
<b>6.4</b>	<b>Universal, individual and moving range chart .....</b>	<b>20</b>
<b>6.4.1</b>	<b>Purpose .....</b>	<b>20</b>
<b>6.4.2</b>	<b>Scope of application .....</b>	<b>20</b>

6.4.3	Method .....	20
6.4.4	Example .....	21
6.5	Universal, moving mean and moving range chart .....	22
6.5.1	Purpose .....	22
6.5.2	Scope of application .....	23
6.5.3	Method .....	23
6.5.4	Example .....	24
Annex A (informative) Reproducible copies of control charts forms and normal probability worksheet .....		25
Bibliography .....		31