

DIN ISO 7870-2:2021-01 (E)

Control charts - Part 2: Shewhart control charts (ISO 7870-2:2013)

Contents

Page

National foreword	4
National Annex NA (informative) Bibliography	5
Foreword	6
Introduction	7
1 Scope	8
2 Normative references	8
3 Terms, definitions and symbols	8
3.1 General	8
3.2 Symbols	8
4 Nature of Shewhart control charts	10
5 Types of control charts	12
5.1 Control charts where no pre-specified values are given	12
5.2 Control charts with respect to given pre-specified values	13
5.3 Types of variables and attributes control charts	13
6 Variables control charts	14
6.1 Mean ($\bar{X}$) chart and range (R) chart or mean ($\bar{X}$) chart and standard deviation (s) chart	15
6.2 Control chart for individuals ($\bar{X}$) and control chart for moving ranges (R_m)	16
6.3 Control charts for medians ($\tilde{X}$)	17
7 Control procedure and interpretation for variables control charts	18
7.1 Collect preliminary data	18
7.2 Examine the s (or R) chart	18
7.3 Remove assignable causes and revise the chart	18
7.4 Examine the $\bar{X}$ chart	19
7.5 Ongoing monitoring of process	19
8 Pattern tests for assignable causes of variation	19
9 Process control, process capability, and process improvement	20
10 Attributes control charts	22
11 Preliminary considerations before starting a control chart	24
11.1 Choice of critical to quality (CTQ) characteristics describing the process to control	24
11.2 Analysis of the process	24
11.3 Choice of rational subgroups	24
11.4 Frequency and size of subgroups	25
11.5 Preliminary data collection	25
11.6 Out of control action plan	25
12 Steps in the construction of control charts	25
12.1 Determine data collection strategy	26
12.2 Data collection and computation	27
12.3 Plotting $\bar{X}$ chart and R chart	27

13	Caution with Shewhart control charts	27
13.1	General caution	28
13.2	Correlated data	29
13.3	Use of alternative rule to the three-sigma rule	29
Annex A (informative)	Illustrative examples	31
Annex B (informative)	Practical notices on the pattern tests for assignable causes of variation	49
Bibliography		51