

# ISO 3951-6:2023-12 (E)

## Sampling procedures for inspection by variables - Part 6: Specification for single sampling plans for isolated lot inspection indexed by limiting quality (LQ)

---

<b>Contents</b>		<b>Page</b>
Foreword .....		v
Introduction .....		vi
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>2</b>
<b>4</b>	<b>Symbols .....</b>	<b>6</b>
<b>5</b>	<b>Choice of a sampling plan .....</b>	<b>7</b>
5.1	Choice between variables and attributes .....	7
5.2	General .....	7
5.3	Choice between the s-method and the -method .....	8
5.4	Choice of the limiting quality (LQ) .....	8
<b>6</b>	<b>Standard procedures for the s-method .....</b>	<b>9</b>
6.1	General .....	9
6.2	Single specification limits .....	9
6.3	Double specification limits .....	9
<b>7</b>	<b>Standard procedures for the -method .....</b>	<b>10</b>
7.1	General .....	10
7.2	Single specification limits .....	10
7.3	Double specification limits .....	10
<b>8</b>	<b>The p*-method .....</b>	<b>11</b>
<b>9</b>	<b>Relation to ISO 2859-2 .....</b>	<b>12</b>
9.1	Similarities .....	12
9.2	Differences .....	12
<b>10</b>	<b>Allowing for measurement uncertainty .....</b>	<b>13</b>
<b>11</b>	<b>Normality, data transformations and outliers .....</b>	<b>13</b>
11.1	Normality .....	13
11.2	Data transformations .....	14
11.3	Outliers .....	14
<b>12</b>	<b>Tables .....</b>	<b>14</b>
12.1	Information about the tables .....	14
<b>13</b>	<b>Examples .....</b>	<b>28</b>
13.1	General .....	28
13.2	Examples for the s-method .....	28
13.3	Examples for the -method .....	33
13.4	Examples for the p*-method .....	36
<b>Annex A (informative)</b>	<b>Procedures for obtaining s and .....</b>	<b>40</b>

<b>Annex B (normative) Accommodating measurement error .....</b>	<b>43</b>
<b>Annex C (informative) Sampling strategies .....</b>	<b>51</b>
<b>Annex D (informative) Operating characteristics for the s-method .....</b>	<b>53</b>
<b>Annex E (informative) Operating characteristics for the -method .....</b>	<b>54</b>
<b>Annex F (informative) Consumer's risks .....</b>	<b>55</b>
<b>Annex G (informative) Producer's risk quality .....</b>	<b>56</b>
<b>Annex H (informative) Construction of acceptance diagrams for double specification limits .....</b>	<b>57</b>
<b>Annex I (informative) Use of the underlying software .....</b>	<b>67</b>
<b>ISO 3951-6:2023(E) Bibliography .....</b>	<b>79</b>