

ISO 3951-6:2023-12 (E)

Sampling procedures for inspection by variables - Part 6: Specification for single sampling plans for isolated lot inspection indexed by limiting quality (LQ)

Contents		Page
Foreword		v
Introduction		vi
1	Scope	1
2	Normative references	1
3	Terms and definitions	2
4	Symbols	6
5	Choice of a sampling plan	7
5.1	Choice between variables and attributes	7
5.2	General	7
5.3	Choice between the s-method and the -method	8
5.4	Choice of the limiting quality (LQ)	8
6	Standard procedures for the s-method	9
6.1	General	9
6.2	Single specification limits	9
6.3	Double specification limits	9
7	Standard procedures for the -method	10
7.1	General	10
7.2	Single specification limits	10
7.3	Double specification limits	10
8	The p*-method	11
9	Relation to ISO 2859-2	12
9.1	Similarities	12
9.2	Differences	12
10	Allowing for measurement uncertainty	13
11	Normality, data transformations and outliers	13
11.1	Normality	13
11.2	Data transformations	14
11.3	Outliers	14
12	Tables	14
12.1	Information about the tables	14
13	Examples	28
13.1	General	28
13.2	Examples for the s-method	28
13.3	Examples for the -method	33
13.4	Examples for the p*-method	36
Annex A (informative)	Procedures for obtaining s and	40

Annex B (normative) Accommodating measurement error	43
Annex C (informative) Sampling strategies	51
Annex D (informative) Operating characteristics for the s-method	53
Annex E (informative) Operating characteristics for the -method	54
Annex F (informative) Consumer's risks	55
Annex G (informative) Producer's risk quality	56
Annex H (informative) Construction of acceptance diagrams for double specification limits	57
Annex I (informative) Use of the underlying software	67
ISO 3951-6:2023(E) Bibliography	79