

DIN ISO 3951-1:2024-08 (E)

Sampling procedures for inspection by variables - Part 1: Specification for single sampling plans indexed by acceptance quality limit (AQL) for lot-by-lot inspection for a single quality characteristic and a single AQL (ISO 3951-1:2022)

Contents	Page
National foreword	4
National Annex NA (informative) Bibliography	5
Foreword	6
Introduction	7
1 Scope	9
2 Normative references	9
3 Terms and definitions	10
4 Symbols	14
5 Choice of a sampling plan	15
5.1 Choice between variables and attributes	15
5.2 General	16
5.3 Choice between the <i>s</i> -method and σ -method	16
5.4 Choice of inspection level and AQL	17
6 Standard procedures for the <i>s</i>-method	18
6.1 General	18
6.2 Single specification limits	18
6.3 Double specification limits	19
7 Standard procedures for the σ-method	19
7.1 General	19
7.2 Single specification limits	19
7.3 Double specification limits	20
8 The <i>p</i>*-method	20
9 Switching between inspection severities	21
9.1 Rules for switching between inspection severities	22
9.2 Records for switching between inspection severities	23
10 Relation to ISO 2859-1	23
10.1 Similarities	23
10.2 Differences	24
11 Allowing for measurement uncertainty	25
12 Normality, data transformations and outliers	25
12.1 Normality	25
12.2 Data transformations	25
12.3 Outliers	26
13 Monitoring and recording of inspection results	26
13.1 Monitoring of inspection results	26
13.2 Process capability and performance assessment	26
13.3 Monitoring of process parameters	26
14 Tables	27
14.1 Form <i>k</i> for single sampling plans: <i>s</i> -method	27
14.2 Form <i>k</i> for single sampling plans: σ -method	33

14.3	Form p^* single sampling plans	39
14.4	Values of f_σ for maximum process standard deviation (MPSD).....	45
14.5	Supplementary acceptance constants for qualifying towards reduced inspection	45
15	Examples	46
15.1	General.....	46
15.2	Examples for the s -method.....	46
15.3	Examples for the σ -method	53
15.4	Examples for the p^* -method.....	57
Annex A	(informative) Procedures for obtaining s and σ	60
Annex B	(informative) Accommodating measurement variability	63
Annex C	(informative) Sampling strategies	68
Annex D	(informative) Operating characteristics for the σ-method	70
Annex E	(informative) Operating characteristic for the s-method - tabulated values for single sampling plans, normal inspection	71
Annex F	(informative) Consumer's risk qualities	80
Annex G	(informative) Producer's risks	87
Annex H	(informative) Construction of acceptance diagrams for double specification limits	95
Annex I	(informative) Use of the underlying software	106
Bibliography	111